

DISHWASHING SERVICE REPORT

Account Name: Customer XYZ

Customer Name: Boss

Site: XYZ Bar & Bistro

Location: DR35 Dishwasher Dispenser - Kitchen

Machine / Model: Washtec Kitchen Dishwasher

Dispenser: TDS Dishwasher

Rack Count: 1234

Date: 29/10/2015

Account Manager: Mark Rhind

Technician: Mark Rhind

DISHMACHINE:

Titration	15
Pre Wash Temperature	
Wash Temperature	55
Final Rinse Temperature	83
Power Rinse Temperature	

	YES	NO	N/A
Wash Pump	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
Curtains	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>
Scraping	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
Wash Arms	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
Racks	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
Power Rinse Pump	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>
Drains	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
Wash Temp Gauge	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
Final Rinse Pump	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

Power Rinse Arms	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>
Final Rinse Temp Gauges	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>
Final Rinse Arms	<input type="radio"/>	<input checked="" type="radio"/>	<input type="radio"/>
Racking	<input type="radio"/>	<input type="radio"/>	<input checked="" type="radio"/>
Fill Valves	<input checked="" type="radio"/>	<input type="radio"/>	<input type="radio"/>

DISHMACHINE INSPECTION:

- | | |
|--|--|
| <input checked="" type="checkbox"/> Inside Machine (scale slime) | <input type="checkbox"/> Curtain Positions |
| <input checked="" type="checkbox"/> Floors by Washer | <input checked="" type="checkbox"/> Drains |
| <input checked="" type="checkbox"/> Trays & Screens | <input checked="" type="checkbox"/> Cabinet Exterior |
| <input checked="" type="checkbox"/> Walls by Washer | <input type="checkbox"/> Stainless Steel |

Comments:

Descaled machine cleaned exterior

RESULTS:

Cups	Good	Flatware	Spotting
Glasses		Flatware Silver	
Dishes	Streaks	Pots & Pans	

Comments:

Spotting and Streaks due to Rinse arms blocked, cleaned out, good to go

WAREWASH DISPENSER:

	YES	NO
Exterior Clean	<input checked="" type="radio"/>	<input type="radio"/>
Squeeze Tubes in order	<input checked="" type="radio"/>	<input type="radio"/>
Feed Lines Labelled	<input checked="" type="radio"/>	<input type="radio"/>
Feed Lines Satisfactory	<input checked="" type="radio"/>	<input type="radio"/>

Comments:

GENERAL REPORT:

	YES	NO
MSDS' present and in good condition	<input checked="" type="radio"/>	<input type="radio"/>
Wall charts present and in good condition	<input checked="" type="radio"/>	<input type="radio"/>
Chemical register present and in good condition	<input type="radio"/>	<input type="radio"/>
PPE available	<input checked="" type="radio"/>	<input type="radio"/>

Comments:

GENERAL COMMENTS:

Rinse arms blocked , cleaned out, showed chef.
Rinse arms being blocked have caused spotting and streaks
Otherwise machine in good working order

URGENT ACTIONS REQUIRED:

DATE TO BE COMPLETED:

n/a